

ZCZCDPQ953

DAN: 450-074327

INPUT CDSN: DK1067

BFN: PA291531

TOR: 291705Z DEC 86

TOT: 291705Z DEC 86

ROUTING= DPG

WIRE SVC= **UNASSIGNED**

COMMDIS=**UNASSIGNED**

RTTUZYUW RUED9FA2314 3631548-UUUU--RUTLAAB.

ZNR UUUUU ZYN ZPO

R 291531Z DEC 86

FM FBIS PM

TO RUTLAAB/FBIS WASHINGTON DC

ACCT FBPA-EWDK

BT

UNCLAS

ATTN

ONLY FSB/FED

SUBJ

REF PA192025

SERVICE: INTERNET EQUIPMENT WEEKLY REPORT

STAT

STAT

PA291531

THE PROBLEM WITH THE STICKING RELAY IN THE ENVIRONMENTAL
CONTROL BOX STILL PERSISTS. EVERY TIME THE SHELTER IS
INSPECTED THE BOX MUST BE TAPPED TO MAKE THE RELAY RELEASE
AND TURN OFF THE AIR CONDITIONER. THIS MORNING, AFTER THE
LONG HOLIDAY WEEKEND, THE TEMPERATURE INSIDE THE SHELTER
WAS 54 DEGREES. EVERYTHING ELSE IS OK. REGARDS.

29/1554Z DEC

STAT

BT

#2314

NNNN